

## 286 Parkland Ave Landscape Plans

### Trees to be removed:

#### Holly tree

Front corner of house - Decision to remove is based on the following 2 points.

- \* Holly tree is showing signs of disease/decline
- \* The terrain needs to be elevated which would stress the tree with unreliable results

*Twin Trees, each Caliper: 9.55"*

#### Weeping Mulberry

Between House and Driveway

- \* No choice but to remove

*Caliper: 5.41"*

#### Japanese Maple

Backyard

- \* No choice but to remove

*Caliper: 8.59"*

### Trees to be added:

#### Japanese Maple

Front corner of house, roughly the same location as the Holly tree

#### Aspen

Backyard located between bedroom and bathroom

- \* This is not on the approved list, are there exceptions? If not River Birch

### Hardscape:

#### Retaining wall

Will use the limestone stones that are currently retaining the side garden along the driveway.

#### Sidyard Steps

Use of large natural flat stones

#### Sidewalks / Porch

Match existing paver stones or use stamped concrete

### Perennial plantings:

#### Front Corner

Full garden plantings to include:

- \* Cornflowers
- \* Varigated Monkey grass
- \* Creeeping Phlox
- \* Sieberian Iris'
- \*Moonbeam

#### Sidyard / Backyard

Depending on the sun

- \* Blue-Star
- \* Iris'
- \* Daisies
- \* Black-Eyed Susans



286 Parkland Ave

